July 2025	Location	Capacity Impact	Available Capacity	Firm Contract Impact	Potential Firm Primary Cuts	Potential Firm Secondary/ITS Cuts
	Emerson Eastbound (LOC# 3833975)					
	Shevlin Station 3 TSA Required Automation Upgrade/Panel Replacement; Deer					
7/10	River Unit 402 Gas Compressor Overhaul; Sta 2 to Sta 3 MFL Tool Run (100-	405 MMcf/d	1,325 MMcf/d	19%	High	High
	line)					
7/11 - 7/14	Shevlin Station 3 TSA Required Automation Upgrade/Panel Replacement; Deer River Unit 402 Gas Compressor Overhaul;	325 MMcf/d	1,405 MMcf/d	16%	High	High
	Shevlin Station 3 TSA Required Automation Upgrade/Panel Replacement; Deer					
7/15	River Unit 402 Gas Compressor Overhaul; Sta 5 to Sta 6 AFD Tool Run (100-	405 MMcf/d	1,325 MMcf/d	19%	High	High
	line)					
	Shevlin Station 3 TSA Required Automation Upgrade/Panel Replacement; Deer					
7/16	River Unit 402 Gas Compressor Overhaul; Sta 5 to Sta 6 EMAT Tool Run (100-	530 MMcf/d	1,200 MMcf/d	27%	High	High
	line)					
7/17 - 7/30	Shevlin Station 3 TSA Required Automation Upgrade/Panel Replacement; Deer		1.405 MMAsf/d	1.00/	Link	Llink
	River Unit 402 Gas Compressor Overhaul;	325 MMcf/d	1,405 MMcf/d	16%	High	High
	Shevlin Station 3 TSA Required Automation Upgrade/Panel Replacement; Deer					
7/31	River Unit 402 Gas Compressor Overhaul; Sta 6 to Sta 7 EMAT Tool Run (200-	380 MMcf/d	1,350 MMcf/d	18%	High	High
	line)					
	Iron River Eastbound (LOC# 38730027)					
7/1 - 7/31	Wakefield Station 7 TSA Required Automation Upgrade/Panel Replacement	235 MMcf/d	1,390 MMcf/d	12%	High	High
	Crystal Falls CS Eastbound (LOC# 3911656)					
7/7 - 7/31	Rapid River Station 9 TSA Required Automation Upgrade/Panel Replacement	33 MMcf/d	1,553 MMcf/d	2%	Low	Low
August 2025	Location	Capacity Impact	Available Capacity	Firm Contract Impact	Potential Firm Primary Cuts	Potential Firm Secondary/ITS Cuts
	Emerson Eastbound (LOC# 3833975)					
8/1 - 8/15	Shevlin Station 3 TSA Required Automation Upgrade/Panel Replacement; Deer River Unit 402 Gas Compressor Overhaul;	325 MMcf/d	1,405 MMcf/d	16%	High	High
8/16 - 8/31	Shevlin Station 3 TSA Required Automation Upgrade/Panel Replacement	209 MMcf/d	1,521 MMcf/d	10%	High	High
	Iron River Eastbound (LOC# 38730027)					
8/1 - 8/31	Wakefield Station 7 TSA Required Automation Upgrade/Panel Replacement	235 MMcf/d	1,390 MMcf/d	12%	High	High
	Crystal Falls CS Eastbound (LOC# 3911656)					
8/1 - 8/17	Rapid River Station 9 TSA Required Automation Upgrade/Panel Replacement	33 MMcf/d	1,553 MMcf/d	2%	Low	Low
8/18	Rapid River Station 9 TSA Required Automation Upgrade/Panel Replacement; Sta 9 to Sta 10 EMAT Tool Run (100-line)	386 MMcf/d	1,200 MMcf/d	12%	High	High
8/19 - 8/31	Rapid River Station 9 TSA Required Automation Upgrade/Panel Replacement	33 MMcf/d	1,553 MMcf/d	2%	Low	Low

Location	Capacity Impact	Available Capacity	Firm Contract Impact	Potential Firm Primary Cuts	Potential Firm Secondary/ITS Cuts
Emerson Eastbound (LOC# 3833975)					
Shevlin Station 3 TSA Required Automation Upgrade/Panel Replacement	209 MMcf/d	1,521 MMcf/d	10%	High	High
Iron River Eastbound (LOC# 38730027)					
Wakefield Station 7 TSA Required Automation Upgrade/Panel Replacement	235 MMcf/d	1,390 MMcf/d	12%	High	High
Crystal Falls CS Eastbound (LOC# 3911656)					
Rapid River Station 9 TSA Required Automation Upgrade/Panel Replacement	33 MMcf/d	1,553 MMcf/d	2%	Low	Low
Location	Capacity Impact	Available Capacity	Firm Contract Impact	Potential Firm Primary Cuts	Potential Firm Secondary/ITS Cuts
Emerson Eastbound (LOC# 3833975)				- -	
Iron River Station 6 Fire and Gas Detection Equipment Replacement and Valve Replacements	215 MMcf/d	1,515 MMcf/d	10%	High	High
Iron River Eastbound (LOC# 38730027)					
Crystal Falls Station 8 Aftercooolers Demolition	283 MMcf/d	1,302 MMcf/d	17%	High	High
Crystal Falls CS Eastbound (LOC# 3911656)					
Rapid River Station 9 TSA Required Automation Upgrade/Panel Replacement	33 MMcf/d	1,553 MMcf/d	2%	Low	Low
	Emerson Eastbound (LOC# 3833975)   Shevlin Station 3 TSA Required Automation Upgrade/Panel Replacement   Iron River Eastbound (LOC# 38730027)   Wakefield Station 7 TSA Required Automation Upgrade/Panel Replacement   Crystal Falls CS Eastbound (LOC# 3911656)   Rapid River Station 9 TSA Required Automation Upgrade/Panel Replacement   Location   Emerson Eastbound (LOC# 3833975)   Iron River Station 6 Fire and Gas Detection Equipment Replacement and Valve Replacements   Iron River Eastbound (LOC# 38730027)   Crystal Falls Station 8 Aftercooolers Demolition   Crystal Falls CS Eastbound (LOC# 3911656)	Emerson Eastbound (LOC# 3833975) Image: Comparison of the comparison of thecomparison of the comparison of the comparison of the	Emerson Eastbound (LOC# 3833975)Addition (LOC# 3833975)Shevlin Station 3 TSA Required Automation Upgrade/Panel Replacement209 MMcf/dIron River Eastbound (LOC# 38730027)1,521 MMcf/dWakefield Station 7 TSA Required Automation Upgrade/Panel Replacement235 MMcf/dCrystal Falls CS Eastbound (LOC# 3911656)1,390 MMcf/dRapid River Station 9 TSA Required Automation Upgrade/Panel Replacement33 MMcf/dLocationCapacity ImpactAvailable CapacityEmerson Eastbound (LOC# 3833975)1,553 MMcf/dIron River Station 6 Fire and Gas Detection Equipment Replacement and Valve Replacements215 MMcf/dIron River Eastbound (LOC# 38730027)215 MMcf/dCrystal Falls CS Eastbound (LOC# 38730027)1,515 MMcf/d	LocationCapacity ImpactAvailable CapacityImpactImpactEmerson Eastbound (LOC# 3833975)ImpactShevlin Station 3 TSA Required Automation Upgrade/Panel Replacement209 MMcf/d1,521 MMcf/dIron River Eastbound (LOC# 38730027)ImpactImpactWakefield Station 7 TSA Required Automation Upgrade/Panel Replacement235 MMcf/d1,390 MMcf/d12%Crystal Falls CS Eastbound (LOC# 3911656)ImpactImpactImpactRapid River Station 9 TSA Required Automation Upgrade/Panel Replacement33 MMcf/d1,553 MMcf/d2%Iron River Station 9 TSA Required Automation Upgrade/Panel Replacement33 MMcf/d1,553 MMcf/d2%Iron River Station 9 TSA Required Automation Upgrade/Panel Replacement33 MMcf/d1,553 MMcf/d1/mpactIron River Station 9 TSA Required Automation Upgrade/Panel Replacement215 MMcf/d1,515 MMcf/d10%Iron River Station 6 Fire and Gas Detection Equipment Replacement and Valve Replacements215 MMcf/d1,515 MMcf/d10%Iron River Eastbound (LOC# 38730027)ImpactImpactImpactCrystal Falls CS Eastbound (LOC# 3911656)ImpactImpactImpactImpact Iron River Eastbound (LOC# 3911656)Impact ImpactImpactImpactImpact Iron River Eastbo	LocationCapacity ImpactAvailable CapacityImpactPrimary CutsEmerson Eastbound (LOC# 3833975) </td